Oil Field Environmental Incident Summary **Date/Time of Notice:** 12/27/2013 17:22 Incident: 20131227174053 Responsible Party: Water Works Well Operator: WATERWORKS CORRAL CREEK, LLC Well Name: Kleeman SWD #1 Field Name: CORRAL CREEK Well File #: 90257 Date Incident: 9/12/2013 Time Incident: 18:00 Facility ID Number: DUNN **Rna**: 95 Sec: 19 Qtr: SW SW County: Twp: 146 Location Description: Submitted By: Ken McGuire Received By: Contact Person: Ken McGuire 828 Hwy 22 N Killdeer, ND 58640 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Pipeline Leak Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown Spilled **Units** Recovered Units Followup **Units** Oil 0 barrels 0 barrels **Brine** 0 barrels 0 barrels Other 5 barrels barrels **Description of Other Released Contaminant: Production Salt Water** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation:

Friday, February 10, 2017 Page 1 of 2

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

Shut well off, put commentated soil on plastic, replaced bad joint of pipe

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/30/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to piping leak remained on location, according to the report. NDIC retains oversight.